



ULTRA COAT

HIGH TRAFFIC FLOOR FINISH

FEATURES

- High solids, low odor floor finish
- Extends recoat and stripping cycles

BENEFITS

- Easy to apply and maintain
- Excellent gloss and outstanding durability
- Resists black marks, scratching & dirt embedment

RECOMMENDED USES

For use on all resilient floors.

SPECIFICATIONS

| | | | |
|------------------|-----------------------------|---------------------------|-----------|
| Color | : White | pH use dilution | : 7.7-8.7 |
| Scent | : None Added | Phosphorus content | : 0.37% |
| Character | : Milky, non-viscous liquid | Solids | : 24.5% |

IMPORTANT:

Read and understand the label and Safety Data Sheet (SDS). These provide a description of hazards, precautions, personal protective equipment, first aid, 24 Hour Emergency lines, storage data and other safe handling information. The SDS is provided with each container shipped. It is also available on our website or from the distributor.



PRODUCT DIRECTIONS

EQUIPMENT TO USE:

Appropriate stripping chemicals and equipment, clean mop, mop bucket, burnishing equipment, deep scrubbing equipment, wet floor signs.

DIRECTIONS FOR USE:

1. Blockade area to be stripped. Floors will be very slippery until dry.
2. Strip floor, using a stripper per the instructions on the stripper label.

COATING:

1. Dust mop or sweep.
2. Allow 30-45 minutes drying time between coats. Temperature, humidity and ventilation may affect drying time.
Allow finish to cure for 24 hours before burnishing.

MAINTENANCE:

1. Dust mop or sweep.
2. Clean the floor with a mop or an automatic scrubber using the recommended cleaner according to label directions.
3. To enhance appearance, use any of the following methods: Dry buff using medium to aggressive pad and 1000-1500 rpm equipment. Ultra-high speed burnish using a medium aggressiveness pad and 2000+ rpm equipment.

RECOATING:

1. Dust mop or sweep.
2. Clean the floor with a mop or an automatic scrubber using the recommended cleaner according to label directions.
3. Blockade area and apply 1-2 uniform coats of finish using a clean mop.
4. Allow finish to cure for 24 hours before burnishing.

REMOVAL:

1. Remove using a floor stripper according to label directions.

PACKAGING

This product is available in a 5 gallon bag-in-box (100957205).